

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

IX1256
East
> 1
1.626 mi.
8586 ft.

MANHOLE 66870
20TH ST/SHORE PKY
BROOKLYN, NY
Site 2 of 2 in cluster IX

NY Spills S103937348
N/A

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name: MANHOLE 66870
Address: 20TH ST/SHORE PKY
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9901806 / 1999-07-20
Facility ID: 9901806
Facility Type: ER
DER Facility ID: 147179
Site ID: 175050
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 1999-05-16
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-05-16
CID: 382
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-05-16
Spill Record Last Update: 2000-06-13
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: JOE DEVOTI
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT Con ed e2mis notes: Approx 1 pint of oil on floor of mh.
6ppm pcb D.Bankhead flush reports cleanup completed. "
Remarks: "clean up pending lab results. con ed 124-920"

All Materials:

Site ID: 175050
Operable Unit ID: 1080568
Operable Unit: 01
Material ID: 305335
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported